

Inspection Photos

Loc: 308057

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/6/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. There is a long stretch of road that concentrates stormwater down the roadside causing erosion.



Inspection Photos



Photo 2. There is a long stretch of road that concentrates stormwater down the roadside causing erosion.



Inspection Photos



Photo 3. Facing southwest back down the access road. This area is eroded and needs to be repaired and stabilized.



Inspection Photos



Photo 4. Facing north along the access road. This area of road is rutting and vehicle track went off road around this area. This area needs to be regraded.



Inspection Photos



Photo 5. Facing southeast toward the wellsite.



Inspection Photos



Photo 6. Facing east along the fill slope which is stabilized with vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308057 | Date: 2/6/2025

Inspection Photos



Photo 7. Facing south toward the production equipment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308057 | Date: 2/6/2025