

**WILLIFORD ENERGY COMPANY
Rhoades Unit Gas Injection Flowline
Facility # 476172**



No signage at entrance.



**WILLIFORD ENERGY COMPANY
Rhoades Unit Gas Injection Flowline
Facility # 476172**



**Stained ground around compressor equipment.
Drums, buckets and jugs with no secondary
containment.**



**Stained ground around compressor equipment.
Drums, buckets and jugs with no secondary
containment.**

**WILLIFORD ENERGY COMPANY
Rhoades Unit Gas Injection Flowline
Facility # 476172**



**Stained ground around compressor equipment.
Drums, buckets and jugs with no secondary
containment.**



**Contaminated material from spill
being stored on location.**