

Inspection Photos

02/05/2025

Operator: VISION ENERGY LLC - 10770

Location ID: 312639

Inspection Doc: 718100264

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312639



February 5, 2025



February 5, 2025

Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Though perennial species were observed, vegetation on location is predominantly annual weedy grass species such as cheatgrass and annual wheatgrass. Site appears to be in process though additional revegetation efforts may be necessary.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312639



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312639



Photo 4: Photo taken from the adjacent reference areas for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources