

Inspection Photos
Location Name: Day 14-35 4N47W
API Number: 125-10974



1. Lease sign at well location.




2. View of wellhead.

Inspection Photos
Location Name: Day 14-35 4N47W
API Number: 125-10974



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Day 14-35 4N47W
API Number: 125-10974



5. Gas meter inside meter shed.



6. Gathering location overview.