

Inspection Photos

February 7th, 2024

Operator: American Helium Operating - 10841

Location ID: 322090

Inspection Document #: 714001798

Dolores County, CO

Township: SWNE 7 38N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cross Canyon Unit 1
Location ID: 322090



2/7/25
190° S

Photo 1. View of the well pad from the access point facing center. Location sign has been updated.



2/7/25
184° S

Inspection Photos
Location Name: Cross Canyon Unit 1
Location ID: 322090

2/7/25
210° SW



Photo 2: Western interim reclamation area composed of Rabbitbrush, Broome Snakeweed and Smooth Broome.

Inspection Photos
Location Name: Cross Canyon Unit 1
Location ID: 322090



Photo 3. Patches of Musk Thistle observed in the western and eastern interim reclamation areas. Evidence that Musk Thistle flowered and went to seed this season.

Inspection Photos
Location Name: Cross Canyon Unit 1
Location ID: 322090

2/7/25
219° SW



Photo 4. Unused oil and gas shed observed on location.

Inspection Photos
Location Name: Cross Canyon Unit 1
Location ID: 322090



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Juniper, Snakeweed and Indian Ricegrass.

API #: 033-06012