

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/28SWNE

Location ID: 335275

Date: 2/6/2025



Location Overview – Photo #06512



Location – Photo #06513



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/28SWNE

Location ID: 335275

Date: 2/6/2025



Location – Photo #06522



Location – Photo #06514



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/28SWNE

Location ID: 335275

Date: 2/6/2025



Location – Photo #06521



Location – Photo #06520



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/28SWNE

Location ID: 335275

Date: 2/6/2025



**Lack of Stabilization – Photo #06523**



**Insufficient Tracking BMPs – Photo #06524**