

Inspection/Audit Photos
Location Name: QB Energy DUNN 9-4 (C9E) Pad
Location #: 334841



Photo # 4563 From entrance to location



Photo # 4564 Location



Inspection/Audit Photos
Location Name: QB Energy DUNN 9-4 (C9E) Pad
Location #: 334841



Photo # 4565 Location




Photo # 4566 Location

Inspection/Audit Photos
Location Name: QB Energy DUNN 9-4 (C9E) Pad
Location #: 334841



Photo # 4567 Location




Photo # 4568 Location

Inspection/Audit Photos

Location Name: QB Energy DUNN 9-4 (C9E) Pad

Location #: 334841



**Photo # 4569 Hole around wellhead lacks wildlife
egress/wildlife hazard**