

# Final Reclamation and Stormwater Inspection

January 31, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 331935

Well Name: PURITAN #34-34

Inspection Document #: 718600260

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PURITAN #34-34  
Location ID: 331935



**Photo 1.** Looking north down former northern access road. This area appears to have had reclamation work conducted and perennial vegetation has established.



**Photo 2.** Looking southeast towards well location.



Inspection Photos  
Location Name: PURITAN #34-34  
Location ID: 331935



**Photo 3.** Looking south across the well location. Orange construction fencing is present around wellbore.



**Photo 4.** An open excavation is present over the wellbore. A flag marked Civitas is present.



Inspection Photos  
Location Name: PURITAN #34-34  
Location ID: 331935



**Photo 5.** Looking west from the wellbore. Fresh piles of soil are present on well location. It appears that perennial vegetation has established on some portions of the location.



**Photo 6.** Looking north from well site. Piles of rubble and debris are present on location.



Inspection Photos  
Location Name: PURITAN #34-34  
Location ID: 331935




**Photo 7.** Looking east from well location down main access road. It appears this road is being used for construction purposes.



**Photo 8.** Reference vegetation west of the well location.

Inspection Photos  
Location Name: PURITAN #34-34  
Location ID: 331935



**Photo 9.** Google earth aerial image taken 09/2021. It appears that reclamation work was conducted on portions of the access road and well location. The entirety of the well location and access road are located in a parcel that appears to be a land use change from cropland to construction.

