

Final Reclamation and Stormwater Inspection

January 31, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 317791

Location Name: WITTEMYER/41-2

Inspection Document #: 718600262

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: WITTEMYER/41-2
Location ID: 317791



Photo 1. Looking west down access road towards wellsite.



Photo 2. Looking north across well location. Undesirable weedy species Kochia and Russian Thistle are present on location.



Inspection Photos
Location Name: WITTEMYER/41-2
Location ID: 317791



Photo 3. Looking north from wellbore area. Location is surrounded by cropland. The well location should return to cropland.



Photo 4. Looking west from wellbore.



Inspection Photos
Location Name: WITTEMYER/41-2
Location ID: 317791



Photo 5. Looking east from wellbore.



Photo 6. Looking northeast from the northeast corner of location. Possible farming access road.



Inspection Photos
Location Name: WITTEMYER/41-2
Location ID: 317791



Photo 7. Historical imagery taken 09/21/1971. Original land use appears to be cropland. Access roads appear to be preexisting to oil and gas (blue arrows). Approximate well location (green circle).