

# Final Reclamation and Stormwater Inspection

February 7, 2025

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 309984

Inspection Document #: 697505793

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: NGL Apollo Facility  
Location ID: 309984



**Photo 1.** ECMC aerial imagery from 2021 illustrates the NGL Apollo Facility, PA DSPW well (123-25694), IJ DSPW well (123-42210) and the Produced Water Transfer System.



Inspection Photos  
Location Name: NGL Apollo Facility  
Location ID: 309984



**Photo 2.** ECMC aerial imagery from 2021 illustrates the PA DSPW well (123-25694) that was PA'ed on 8/17/2015 and the associated facility (circled in red) that is no longer in use. Note- the Produced Water Transfer System In-Service Date started on 12/20/2015.



Inspection Photos  
Location Name: NGL Apollo Facility  
Location ID: 309984



**Photo 3.** Photo taken of the northern facility that is no longer in use, facing North. Photo also illustrates unused equipment. Refer to Photo 4 regarding the red arrow.



Inspection Photos  
Location Name: NGL Apollo Facility  
Location ID: 309984



Photo 4. Photo taken of a produced water tank with stating it is permanently closed.

