

Inspection Photos

February 7th, 2024

Operator: American Helium Operating - 10841

Location ID: 322102

Inspection Document #: 714001805

Dolores County, CO

Township: NESW 17 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ranger Federal 12-17
Location ID: 322102



Photo 1. View of the well pad from the access point facing center. Location sign has been updated with current operator information.



API #: 033-06072

Inspection Photos
Location Name: Ranger Federal 12-17
Location ID: 322102

2/7/25
42° NE



Photo 2: Weeds encroaching on wellhead equipment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 033-06072

Inspection Photos
Location Name: Ranger Federal 12-17
Location ID: 322102



Photo 3. Weeds within tank berm. Note: new NFPA tank labels have been installed.