

Inspection Photos

February 7th, 2024

Operator: American Helium Operating - 10841

Location ID: 322103

Inspection Document #: 714001807

Dolores County, CO

Township: SWSW 8 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hugus Federal 1
Location ID: 322103



Photo 1. View of the well pad from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 033-06076

Inspection Photos
Location Name: Hugus Federal 1
Location ID: 322103



Photo 2: Produced water tank NFA labels are too dark and not legible.



Inspection Photos
Location Name: Hugus Federal 1
Location ID: 322103



Photo 3. Vegetation/weedy debris observed encroaching on wellhead and tank berms.

2/7/25
126° SE



Photo 4. Interim reclamation area composed of Rabbitbrush, Broom Snakeweed and Smooth Brome.

2/7/25
9° N



Photo 5. Reference area composed of Black Sagebrush, Yucca, Juniper and James Galleta.