

Inspection Photos

February 7th, 2024

Operator: American Helium Operating - 10841

Location ID: 322094

Inspection Document #: 714001808

Dolores County, CO

Township: SENE 7 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Santa Fe Canyon Fed. 42-7
Location ID: 322094

2/7/25
92° E



2/7/25
321° NW

Photo 1. View of the well pad from the access point facing center. Location sign has been updated with current operator information.

Inspection Photos
Location Name: Santa Fe Canyon Fed. 42-7
Location ID: 322094



Photo 2: Vegetation encroaching on tank berms, at separator and wellhead equipment.



Photo 3. Large patch of Cheatgrass observed around produced water tank berms and throughout interim reclamation areas.

2/7/25
100° E



Photo 4. Interim reclamation area composed of Rabbitbrush, Western Wheatgrass and Sand Dropseed.

2/7/25
9° N



Photo 5. Reference area composed of Black Sagebrush, Yucca, Juniper and James Galleta.