

Inspection Photos

February 7th, 2024

Operator: American Helium Operating - 10841

Location ID: 322097

Inspection Document #: 7140018010

Dolores County, CO

Township: SESW 7 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ranger Federal 24-7
Location ID: 322097



2/7/25
271° W



2/7/25
355° N

Photo 1. View of the well pad from the access point facing center. Location sign has been updated with current operator information.

2/7/25
130° SE



Photo 2: Unused riser equipment observed on the southern edge of the pad.

Inspection Photos
Location Name: Ranger Federal 24-7
Location ID: 322097

2/7/25
238° SW



Photo 3. Interim reclamation area composed of Sand Dropseed, Rabbitbrush and Crested Wheatgrass.

2/7/25
11° N



Photo 4. Reference area composed of Smooth Brome, Sagebrush and Mustard.