

Inspection Photos

Loc: 483008

Operator: BNL (ENTERPRISE) INC

Inspection Date: 2/10/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. There is equipment that appears to be installing flowlines.



Inspection Photos



Photo 2. Facing northeast along the access road. There are areas of the road that will need to be repaired and stabilized. Vehicles are driving around the damaged area of the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483008 | Date: 2/10/2025

Inspection Photos



Photo 3. Facing northeast along the access road. There are areas of the road that will need to be repaired and stabilized. Vehicles are driving around the damaged area of the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483008 | Date: 2/10/2025

Inspection Photos



Photo 4. Facing northeast toward the access road. The side of the road and location was recently drill seeded.



Inspection Photos



Photo 5. Facing northwest toward the location. Interim reclamation has been performed. Crews were getting ready to apply straw mulch at the time of inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483008 | Date: 2/10/2025

Inspection Photos



Photo 6. Facing southeast toward the wellhead.



Inspection Photos



Photo 7. North side of the location facing east. Drill seeding was performed perpendicular to the slope.



Inspection Photos



Photo 8. North side of the location facing west. The sign is in disrepair and should be installed at the wellhead.

