

Final Reclamation and Stormwater Inspection

February 7, 2025

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 443273

Inspection Document #: 697505796

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: NGL Apollo 11
Location ID: 443273



Photo 1. ECMC aerial imagery from 2021 illustrates the NGL Apollo Facility, PA DSPW well (123-25694), IJ DSPW well (123-42210) and the Produced Water Transfer System.



Inspection Photos
Location Name: NGL Apollo 11
Location ID: 443273



Photo 2. ECMC aerial imagery from 2021 illustrates the active southern facility, IJ DSPW well (123-42210) and the Produced Water Transfer System.



Inspection Photos
Location Name: NGL Apollo 11
Location ID: 443273



Photo 3. Photo taken of the eastern facility, facing North. Photo illustrates an unused tarp and unknown gravel material.



Inspection Photos
Location Name: NGL Apollo 11
Location ID: 443273



Photo 4. Photo taken of the eastern facility, facing North. Photo illustrates what appears to be a topsoil stockpile, which the Operator plans to reseed this Spring 2025.



Inspection Photos
Location Name: NGL Apollo 11
Location ID: 443273



Photo 5. Photo taken of the eastern facility, facing South. Photo illustrates unused equipment being stored on location.