

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5001 From entrance to location**



**Photo # 5002 From entrance to location**

Inspection/Audit Photos  
Location Name: QB Energy HILL 16-2D (B16E) Pad  
Location ID: 334951



Photo # 5003 Location



Photo # 5004 Location

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



Feb 11, 2025 at 11:15:24 AM  
CO



Feb 11, 2025 at 11:15:54 AM  
CO

**Photo # 5005 Location**

**Photo # 5006 Location**

Inspection/Audit Photos  
Location Name: QB Energy HILL 16-2D (B16E) Pad  
Location ID: 334951



Photo # 5007 Location




Photo # 5008 Flowline heating insulation open ended /wildlife hazard/available for entry by wildlife

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5009 Flowline heating insulation open ended  
/wildlife hazard/available for entry by wildlife**



**Photo # 5010 HILL 16-3 well - intermediate casing annulus  
inaccessible**

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5011 HILL 9-14C well - intermediate casing annulus inaccessible**



**Photo # 5012 HILL 16-2D well - intermediate casing annulus inaccessible**

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5013 Unmarked deadman**



**Photo # 5014 Same unmarked deadman**

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5015 Hole in liner/liner needs maintenance**

**Photo # 5016 Hole in liner/liner needs maintenance**

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5017 Hole in liner/liner needs maintenance**



**Photo # 5018 Hole in liner/liner needs maintenance**

**Inspection/Audit Photos**  
**Location Name: QB Energy HILL 16-2D (B16E) Pad**  
**Location ID: 334951**



**Photo # 5019 Hole in liner/liner needs maintenance**



**Photo # 5020 Hole in liner/liner needs maintenance**