

## Inspection Photos

Location Name: North Platte/33-13

Location #: 310742



**Photo #1**

**North Platte 34-13 (123-35146) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 35 yds.*



**Photo #2**

**Champlin 1-13, North Platte 33-13, 34-13, S-13**

**Battery site**

**Abandoned: ALL Equipment Removed**

**Plugged & Abandoned | PA (4-Wells)**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources