

Inspection Photos

Location Name: North Platte/33-13

Location #: 310742



Photo #1

North Platte S-13 (123-35139) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 40 yds.



Photo #2

Champlin 1-13, North Platte 33-13, 34-13, S-13

Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (4-Wells)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources