

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32SWNE

Location ID: 324138

Date: 2/11/2025



Location – Photo #06613



Rill Erosion on Access Road – Photo #06615

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32SWNE

Location ID: 324138

Date: 2/11/2025



Rill Erosion on Access Road – Photo #06616