

Inspection/Audit Photos
Location Name: QB Energy MAGIC 10-2 (P3) Pad
Location ID: 334590



Photo # 5626 From entrance to location



Photo # 5627 From entrance to location

Inspection/Audit Photos
Location Name: QB Energy MAGIC 10-2 (P3) Pad
Location ID: 334590




Photo # 5628 Location



Photo # 5629 Location



Inspection/Audit Photos
Location Name: QB Energy MAGIC 10-2 (P3) Pad
Location ID: 334590



Photo # 5630 Location



Photo # 5631 Location

Inspection/Audit Photos
Location Name: QB Energy MAGIC 10-2 (P3) Pad
Location ID: 334590



Photo # 5632 Location




Photo # 5633 Location

Inspection/Audit Photos
Location Name: QB Energy MAGIC 10-2 (P3) Pad
Location ID: 334590



Photo # 5634 Location



Photo # 5635 Location

Inspection/Audit Photos
Location Name: QB Energy MAGIC 10-2 (P3) Pad
Location ID: 334590



Photo # 5636 Location



Photo # 5637 Small amount of staining in secondary containment