



Inspection Photos

Location Name: Powder Wash

Camp Lateral 118

Facility ID: 489200

Inspection Date: 12/11/2024

Photo#1 section of failed pipe was replaced at the time of this photo.

Jan 31, 2025 11:42 41 AM
40.94603239092976N 108.3081721700728W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jan 31, 2025 11:44:52 AM
40.94602924771607N 108.30817082896829W
505 Cedar Drive
Craig
Moffat County
Colorado

Inspection Photos
Location Name: Powder Wash
Camp Lateral 118
Facility ID: 489200
Inspection Date: 12/11/2024

Photo#2 looking below
the failed section of pipe
where fluid daylighted
and flowed downhill.
Note: Wexpro office in
background.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources