

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404095133

Date Received:

02/15/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001742

Inspection Date: 01/24/2025

FIR Submit Date: 01/29/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325665

Location Name: BEUTEN GAS UNIT A-N33N7W Number: 29NENE County: _____

Qtrqr: NENE Sec: 29 Twp: 33N Range: 7W Meridian: N

Latitude: 37.079340 Longitude: -107.626581

FACILITY - API Number: 05-067-00 Facility ID: 325665

Facility Name: BEUTEN GAS UNIT A-N33N7W Number: 29NENE

Qtrqr: NENE Sec: 29 Twp: 33N Range: 7W Meridian: N

Latitude: 37.079340 Longitude: -107.626581

CORRECTIVE ACTIONS:

1 CA# 202149

Corrective Action: Comply with rule 606. remove unused oil and gas equipment.

Date: 03/01/2025

Response: CA COMPLETED

Date of Completion: 02/13/2025

Operator Comment: Unused equipment removed.

ECMC Decision: _____

label installed.

Corrective actions completed. See attachment for photos.

Signed: _____

Date: 2/15/2025 10:13:19 AM

<u>Document Number</u>	<u>Description</u>
404095133	FIR RESOLUTION SUBMITTED
404095134	Beuten A1 CA photos

Page 2 of 2