

Inspection Photos

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325490

Inspection Document #: 714001859

La Plata County, CO

Township: NWSW 29 34N 6W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490

2/13/25
299° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of weedy Kochia debris lining the location perimeter.

API #: 067-06483

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490



Photo 3. View of wellhead assembly, no weeds/vegetation observed encroaching on wellhead.

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490



Photo 4. View of produced water tank berm, no weedy debris/vegetation observed.

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490

2/13/25
152° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of interim reclamation area composed of Rabbitbrush and Western Wheatgrass.

API #: 067-06483

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490



Photo 6. View of access road, no stormwater issues were observed.

Inspection Photos
Location Name: Pine River 2-29 2
Location ID: 325490



2/13/25
202° S

Photo 7. Reference area composed of Four Winged Saltbush, Juniper, Crested Wheatgrass and Western Wheatgrass.