

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404103930

Date Received:

02/24/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001722

Inspection Date: 01/14/2025

FIR Submit Date: 01/22/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326341

Location Name: BONAFACIO GALLEGOS GAS UNIT -N33N8W Number: 2NWSE County: _____

Qtrqr: NWSE Sec: 2 Twp: 33N Range: 8W Meridian: N

Latitude: 37.129959 Longitude: -107.686033

FACILITY - API Number: 05-067- -00 Facility ID: 326341

Facility Name: BONAFACIO GALLEGOS GAS UNIT -N33N8W Number: 2NWSE

Qtrqr: NWSE Sec: 2 Twp: 33N Range: 8W Meridian: N

Latitude: 37.129959 Longitude: -107.686033

CORRECTIVE ACTIONS:

1 CA# 201944

Corrective Action: Comply with rule 1003.f, treat/remove weeds.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/24/2025

Operator Comment: Musk thistle removed.

ECMC Decision: _____

Communication with inspector CM about culvert belonging to Logos.

ECMC Decision: _____

Corrective actions completed. See attachment for photos.

Date: 2/24/2025 11:01:34 AM

<u>Document Number</u>	<u>Description</u>
404103930	FIR RESOLUTION SUBMITTED
404103945	Bonifacio Gallegos A1 completion photos

Page 2 of 2