

WELL NAME: ANDREW 23-15, API #: 071-08460, INSP. # 716300582




PHOTO 1: WELL SIGN





**PHOTO 2: LOCATION.**





**PHOTO 3: WELLHEAD AND EQUIPMENT.**





**PHOTO 4: OILY WASTE IN PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 2-26-2025**






**PHOTO 5: OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 2-26-2025**





**PHOTO 6: AREA OF IMPACTED SOIL AROUND PRIME MOVER ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 3-2-2025.**





**PHOTO 7: AREA OF IMPACTED SOIL AROUND PRIME MOVER ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 3-2-2025.**