

Interim Reclamation and Stormwater Inspection

February 24, 2025

Operator: KP KAUFFMAN COMPANY INC

Location ID: 446484

Location Name: GRANT/

Inspection Document #: 718600320

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GRANT/
Location ID: 446484



Photo 1. Looking east across tank battery location. Undesirable weed Kochia is present throughout location. Location appears to have large areas no longer required for production.



Photo 2. Looking south from the west side of location. Equipment appears to be unused.



Inspection Photos
Location Name: GRANT/
Location ID: 446484



Photo 3. Separator on west side of location. Appears to be unused.



Photo 4. Unused equipment, pipe fittings, unused tank remain.



Inspection Photos
Location Name: GRANT/
Location ID: 446484



Photo 5. Looking east from midpoint of tank battery. Excavation has been filled. Pipe risers/ monitoring wells are present around location.



Photo 6. Looking at the east side of location. Chemical barrel outside of secondary containment (red circle).



Inspection Photos
Location Name: GRANT/
Location ID: 446484



Photo 7. Tank on east side of location appears to be unused.



Photo 8. Inside shed, oily waste is present around equipment.



Inspection Photos
Location Name: GRANT/
Location ID: 446484



Photo 9. Unused equipment and supplies stored in the shed.



Photo 10. Secondary containment around partially buried produced water vessel is insufficient. The western side does not have a gravel berm and liquid could run out through the gap in the shed wall (red circle).

