

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott Pad/41C-36-692

Location ID: 427016

Date: 2/27/2025



Location – Photo #06942



Location – Photo #06944

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott Pad/41C-36-692

Location ID: 427016

Date: 2/27/2025



Location – Photo #06949




Location – Photo #06946

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott Pad/41C-36-692

Location ID: 427016

Date: 2/27/2025



Tank Label Peeling Off – Photo #06954



Tank Label Peeling Off – Photo #06956



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Scott Pad/41C-36-692

Location ID: 427016

Date: 2/27/2025



Stored Supplies – Photo #06959

