

# Inspection Photos

March 5, 2025

Operator: Holcomb Oil and Gas

Location ID: 325522

Inspection Document #: 714001915

La Plata County, CO

Township: NESE 4 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Hurt 1-4  
Location ID: 325522



3/5/25  
124° SE



3/5/25  
324° NW

**HOLCOMB OIL & GAS, INC.**  
HURT 1-4  
LEASE: C-17216  
SEC.4, T34N, R8W NORTH of UTE LINE  
1040' FEL & 1540' FSL (NE/4 of SE/4)  
IGNACIO-BLANCO FIELD, LAPLATA COLO.  
EMERGENCY: 505-326-0550 911

**OPERATOR**

Photo 1. View of well pad taken from the access point facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06545

Inspection Photos  
Location Name: Hurt 1-4  
Location ID: 325522



**Photo 2.** View of western interim reclamation/fill slope area which remains with bare soils and minimal vegetation establishment. Temporary stormwater BMPs need to be installed, additional reclamation/seeding efforts are needed.

Inspection Photos  
Location Name: Hurt 1-4  
Location ID: 325522



**Photo 3.** Large patch of musk thistle observed in western interim reclamation/fill slope.



Inspection Photos  
Location Name: Hurt 1-4  
Location ID: 325522



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Vegetation is progressing in northern cut/interim reclamation area.

API #: 067-06545

Inspection Photos  
Location Name: Hurt 1-4  
Location ID: 325522

3/5/25  
61° NE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Indian Ricegrass, Western Wheatgrass, Grama and Sagebrush.

API #: 067-06545