

Inspection Photos

March 5th, 2025

Operator: Simcoe LLC - 10749

Location ID: 306878

Inspection Document #: 714001920

La Plata County, CO

Township: SWSW 22 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McManus 33-22 2
Location ID: 306878



Photo 1. View of the well pad from the access point facing center. Note: location sign is not displaying current operator.



Inspection Photos
Location Name: McManus 33-22 2
Location ID: 306878



Photo 2. Labels at separator equipment have deteriorated and are no longer legible.

3/5/25
151° SE

