

Inspection Photos

March 5th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326349

Inspection Document #: 714001921

La Plata County, CO

Township: NENW 27 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lamke A1, A3
Location ID: 326349



Photo 1. View of the well pad from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07890, 09761

Inspection Photos
Location Name: Lamke A1, A3
Location ID: 326349



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of weedy kochia debris on the western edge of the active pad.

API #: 067-07890, 09761

Inspection Photos
Location Name: Lamke A1, A3
Location ID: 326349



Photo 3. Stained soils at wellhead #3.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07890, 09761

Inspection Photos
Location Name: Lamke A1, A3
Location ID: 326349

3/5/25
214° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Interim reclamation area composed of Western Wheatgrass, Crested Wheatgrass and Sand Dropseed.

API #: 067-07890, 09761