

# Inspection Photos

March 5th, 2025

Operator: Simcoe LLC - 10749

Location ID: 333844

Inspection Document #: 714001922

La Plata County, CO

Township: NENW 34 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Hronich 21-34 1, 3  
Location ID: 333844

3/5/25  
35° NE



Photo 1. View of the well pad from the access point facing center.



Inspection Photos  
Location Name: Hronich 21-34 1, 3  
Location ID: 333844



**Photo 2.** Weedy kochia debris observed in the northwest corner and southern edge of the pad.

3/5/25  
4° N



**Photo 3.** Produced water tank label is peeling and illegible.

