


Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 3/4/2025



Mar 4, 2025 at 11:42:31
Parachute CO 81635
United States

Location – Photo #06985



Mar 4, 2025 at 11:43:12
Parachute CO 81635
United States

Location – Photo #06986

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 3/4/2025



Location – Photo #06984



Location – Photo #06987

Inspection Photos

Location Name: CAERUS PICEANCE LLC, DAYBREAK FEDERAL/30-12 (PL30)

Location ID: 414077

Date: 3/4/2025



Wildlife Entry Hazard – Photo #06988



Wildlife Entry Hazard – Photo #06991

