

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/29SESW

Location ID: 324346

Date: 3/4/2025



Mar 4, 2025 at 12:05:55
Parachute CO 81635
United States

Location Overview – Photo #06999



Mar 4, 2025 at 12:08:31
Parachute CO 81635
United States

Location – Photo #07004

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/29SESW

Location ID: 324346

Date: 3/4/2025



Location – Photo #07002



Location – Photo #07007

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/29SESW

Location ID: 324346

Date: 3/4/2025



Mar 4, 2025 at 12:10:24
Parachute CO 81635
United States

Location – Photo #07008



Mar 4, 2025 at 12:06:10
Parachute CO 81635
United States

Location – Photo #07000

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/29SESW

Location ID: 324346

Date: 3/4/2025



Wildlife Safety Hazard – Photo #07006



Wildlife Safety Hazard – Photo #07005

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/29SESW

Location ID: 324346

Date: 3/4/2025



Open-Ended Line – Photo #07009

