

Final Reclamation and Stormwater Inspection

Date: 03/05/2025

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 306049

Inspection Document #: 718700171

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn 11-12
Location ID: 306049



Photo 1. Stormwater erosion degradation observed at the former location entrance/access road, which does not appear to have been reclaimed (e.g. road base, contour and grading issues).

Inspection Photos
Location Name: Pronghorn 11-12
Location ID: 306049



Photo 2. Subsidence observed on the west side of the former location entrance.

Inspection Photos
Location Name: Pronghorn 11-12
Location ID: 306049



Photo 3. Taken from the eastern portion of the reclaimed location, near former tank battery. The location appears to be progressing towards reclamation standards with desirable vegetation observed.

Inspection Photos
Location Name: Pronghorn 11-12
Location ID: 306049



Photo 4. Taken from the western portion of the reclaimed location, near former well location. The location appears to be progressing towards reclamation standards with desirable vegetation observed.

Inspection Photos
Location Name: Pronghorn 11-12
Location ID: 306049



Photo 5. Taken from the southern portion of the reclaimed location. The location appears to be progressing towards reclamation standards with desirable vegetation observed.