

## Inspection/Audit Photos

Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad

Location ID: 335423



Photo # 1555 From entrance to location



Photo # 1556 Location

## Inspection/Audit Photos

Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad

Location ID: 335423



Photo # 1557 Location



Photo # 1558 Location





## Inspection/Audit Photos

Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad

Location ID: 335423



Photo # 1559 Location



Photo # 1560 Location



**Inspection/Audit Photos**  
**Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad**  
**Location ID: 335423**



Mar 10, 2025 at 11:19:18 AM  
CO

**Photo # 1561 Location**



Mar 10, 2025 at 11:19:27 AM  
CO

**Photo # 1562 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad**  
**Location ID: 335423**



**Photo # 1563 Location**



**Photo # 1564 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad**  
**Location ID: 335423**



**Photo # 1565 Unmarked deadman**



**Photo # 1566 Same unmarked deadman**



## Inspection/Audit Photos

Location Name: QB Energy SHIDELER 29-11 (K29NE) Pad

Location ID: 335423



**Photo # 1567 Battery lacks required signage/not in compliance with CECMC rules**