

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535

Mar 10, 2025 at 12:29:29 PM



Missing information

Mar 10, 2025 at 12:29:37 PM



Missing information



GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Unmarked anchor



Staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Debris



Open to wildlife

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Missing required information



Debris

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Staining



Staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Staining



Open to wildlife and staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Open to wildlife




Staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Debris and staining



Staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Unused equipment



Debris

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535




Missing required information



Unused equipment

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Missing required information



Oily waste and staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Staining



Staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535




Missing required information



Staining



GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Spill and staining



Debris

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Staining



Debris

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Staining



Staining

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Staining



Open to wildlife

**GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535**



Staining



Damaged loadout pot

**GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535**



Staining inside berm at loadout



Location from North entrance

GRMR Oil & Gas LLC
Deal Gulch 1-16
Location ID: 428535



Location from East corner



Location from South corner