

Inspection Photos

Loc #: 487587

Operator: DESERT EAGLE OPERATING

Inspection Date: 3/13/2025

County: Las Animas



Inspection Photos



Photo 1. Facing southeast along the access road prior to surface disturbance.



Inspection Photos



Photo 2. Facing south following tracks to the location. AS portion of the access road will need to be built to access the wellsite.



Inspection Photos



Photo 3. Facing south at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 487587 | Date: 3/13/2025

Inspection Photos



Photo 4. Facing north at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 487587 | Date: 3/13/2025