

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 1: Wellhead Sign

Photo 2: Wellhead

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 3: Dead, overgrown vegetation and debris

Photo 4: Dead, overgrown vegetation and debris

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 5: Wellhead Sign

Photo 6: Wellhead

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 7: Dead, overgrown vegetation and debris

Photo 8: Dead, overgrown vegetation and debris

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 9: Location from entrance

Photo 10: Erosion

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 11: Erosion

Photo 12: Gas meter OFF

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 13: Unused gas meter

Photo 14: Tank Battery Sign

Inspection Photos  
Location Name: Five M E28-67HN, E28-69HN  
Location ID: 426799



Photo 9: Tank Battery