

**Operator: BONANZA CREEK ENERGY OPERATING
COMPANY**

Location Name: State Whitetail 44-1

Loc ID: 423225

Inspection: 697505802

CA: The location and access road meet final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. The location and access road are reflective of reference area vegetation. However, Operator failed to remove the culvert at the entrance adjacent to CR85. Comply with Rule 1004.a. to remove the culvert. Operator shall submit a FIRR per Rule 210.b documenting that the culvert has been removed.

CA Resolution: Operator has addressed the issue in order to comply with Rule 1004.a.