

Inspection Photos

03/17/2025

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 426478

Inspection Doc: 718100318

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 3: Photos taken from the wells. Photo shows open pipe missing BMPs to prevent wildlife access to the pipe.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 4: Photos taken from next to the STORY GULCH #8505C-24 L24496. Photo shows a rat, mouse, or some other borehole that has not been properly closed/backfilled pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 5: Debris at and around methanol tank on the east end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 6: Photo taken from the southwest end of the Location. Photo shows signage pursuant to Rule 605.e has not been posted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 426478



Photo 7: Photo shows tank label posted on the back of the tank pursuant to Rule 605.h



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources