

Final Reclamation and Stormwater Inspection

March 11, 2025

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 320179

Well Name: GREEN #1

Inspection Document #: 718600379

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GREEN #1
Location ID: 320179



Photo 1. Looking east down access road. Two gates, gravel and culvert remain in place. Access road appears to be primary access to property. Undesirable weed Kochia is present along the access road.



Photo 2. Looking east down former access road near well location. This section of access road appears to have had reclamation work conducted. Larger patches of bare soil are present with little desirable vegetation establishment.

Inspection Photos
Location Name: GREEN #1
Location ID: 320179



Photo 3. Overview of location. Looking south across former tank battery and well location from north side of location on access road. Undesirable weeds Kochia and Russian Thistle are present throughout the location. There appears to be very little desirable vegetation establishment.



Photo 4. Looking south across tank battery from the north edge of battery. No oil and gas equipment remains. See photo 3 comments.

Inspection Photos
Location Name: GREEN #1
Location ID: 320179



Photo 5. Looking south across the wellbore. No oil and gas equipment remains. See photo 3 comments.



Photo 6. Looking east from wellbore. See photo 3 comments.



Inspection Photos
Location Name: GREEN #1
Location ID: 320179



Photo 7. Looking north from wellbore. See photo 3 comments.



Photo 8. Looking west from wellbore. See photo 3 comments.



Inspection Photos
Location Name: GREEN #1
Location ID: 320179



Photo 9. Photo taken from the west side of location looking southeast. Illustrating difference in vegetation from reclaimed area to pasture. (To the right of blue line is pasture).



Photo 10. Reference vegetation to the east of well location within pasture. Vegetation is relatively poor however there are desirable perennial species present.



Inspection Photos
Location Name: GREEN #1
Location ID: 320179



Photo 11. Google aerial imagery taken 09/2023. Illustrating large reclamation area due to remediation project. (Green outline former tank battery and well footprint).