

# Inspection Photos

API: 071-07312

Operator: WAPITI OPERATING LLC

Inspection Date: 3/20/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing north toward the wellsite.



## Inspection Photos



**Photo 2.** Facing northeast toward the meter shed. There is a produced water leak coming from the meter shed that needs to be fixed and cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-07312 | Date: 3/20/2025

## Inspection Photos



**Photo 3.** There is a dripping water leak at the meter shed. The base of the meter shed is all rusted out from the ongoing leak.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-07312 | Date: 3/20/2025

## Inspection Photos



**Photo 4.** There is a hydrocarbon stain at the backside of the meter shed that needs to be cleaned up..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-07312 | Date: 3/20/2025