

TEP
GGU 6-31
Location ID: 334881



Tank battery



Access road signage beginning to fade.

TEP
GGU 6-31
Location ID: 334881



Tank battery



Well heads



TEP
GGU 6-31
Location ID: 334881



Well heads



Separators

TEP
GGU 6-31
Location ID: 334881



Tank signage falling off



Tank signage illegible quantity

TEP
GGU 6-31
Location ID: 334881



ECD not metered



Methanol tank in containment



TEP
GGU 6-31
Location ID: 334881



Staining



Staining

TEP
GGU 6-31
Location ID: 334881



**Location shows sins of lack of stabilization/
compaction**



**Location shows sins of lack of stabilization/
compaction**

TEP
GGU 6-31
Location ID: 334881



Cut slope not stabilized and show areas of erosion.



Cut slope not stabilized and show areas of erosion.

TEP
GGU 6-31
Location ID: 334881



Cut slope not stabilized and show areas of erosion.



Debris

