

Inspection Photos

03/17/2025

Operator: CAERUS PICEANCE LLC - 10456 /
QB ENERGY OPERATING LLC - 10844

Location ID: 425805

Inspection Doc: 718100327

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 1: Photos examples showing subsidence issues observed at the wells on Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 3: Photos examples showing a rat, mouse, or other bore hole that has not been properly closed/backfilled pursuant to 1003 requirements.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 5: Photo taken from the tank facility on the east end of the Location. Photo shows containment BMP has received significant damage, and it is not clear if BMP is in proper functioning condition, or sufficiently impervious to contain a spill or release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 6: Photo taken from the southwest end of the Location. Photo shows unused Gas Meter/Lift and riser equipment; equipment requires removal pursuant to Rule 606

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 7: See comments under photo 6



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 8: Photos 8-9 taken from the interim areas of the Location. Vegetation observed are predominantly perennial grass species. Noxious weeds not apparent at time of inspection. Vegetation appears to be progressing towards ECMC 1003 uniform perennial vegetative cover requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456 / QB ENERGY OPERATING LLC - 10844

Location ID: 425805



Photo 10: See comments under photo 9.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources