

# Final Reclamation Inspection

March 19, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327377

Inspection Document #: 718800050

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CHAMPLIN 86 AMOCO Q #1  
Location ID: 327377



**Photo 1.** Google Earth aerial imagery from June 2, 2014. Photo illustrates the well location, access road, and associated tank battery during active operations.

Inspection Photos  
Location Name: CHAMPLIN 86 AMOCO Q #1  
Location ID: 327377



**Photo 2.** Google Earth aerial imagery from March 2, 2025. Photo illustrates the well location, access road, and associated tank battery after plugging operations. This imagery illustrates that the location is contained within a land use change.

Inspection Photos  
Location Name: CHAMPLIN 86 AMOCO Q #1  
Location ID: 327377



**Photo 3.** Photo taken from the well location, facing North. Photo illustrates that the well location is contained within a land use change from cropland to a residential development.



**Photo 4.** Photo taken from the well location, facing East. See comments under Photo 3.



Inspection Photos  
Location Name: CHAMPLIN 86 AMOCO Q #1  
Location ID: 327377



**Photo 5.** Photo taken from the well location, facing South. See comments under Photo 3.



**Photo 6.** Photo taken from the well location, facing West. See comments under Photo 3.