

# Inspection Photos

March 24th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326198

Inspection Document #: 714001990

La Plata County, CO

Township: SESE 36 33N 11W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Eldridge 36-02 1  
Location ID: 326198



Photo 1. View of well pad taken from the access point facing center.



Inspection Photos  
Location Name: Eldridge 36-02 1  
Location ID: 326198



**Photo 2.** Weedy debris observed on active pad and lining active pad perimeter.



Inspection Photos  
Location Name: Eldridge 36-02 1  
Location ID: 326198





Inspection Photos  
Location Name: Eldridge 36-02 1  
Location ID: 326198



**Photo 4.** Trash along sound wall has been removed.



Inspection Photos  
Location Name: Eldridge 36-02 1  
Location ID: 326198



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Weedy debris encroaching on wellhead.

API #: 067-07631