

Inspection Photos

March 24th, 2025

Operator: Simcoe LLC - 10749

Location ID: 325188

Inspection Document #: 714001992

La Plata County, CO

Township: NWSE 25 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ada 1 EPA
Location ID: 325188



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Ada 1 EPA
Location ID: 325188



Photo 2. Stormwater and unused shed corrective actions have been addressed.

Inspection Photos
Location Name: Ada 1 EPA
Location ID: 325188



Photo 3. Produced water tank labels are starting to peel, future maintenance is advised.

