

Inspection Photos

March 24th, 2025

Operator: BMG Drilling Corporation - 7650

Location ID: 325299

Inspection Document #: 714001996

La Plata County, CO

Township: NWNW 10 33N 910W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DL Gould Flume Canyon 2
Location ID: 325299



Photo 1. View of the project area taken from the western edge facing east. Note: location has not been reclaimed to 1004 standards including but not limited too vegetation and recontouring requirements.

Inspection Photos
Location Name: DL Gould Flume Canyon 2
Location ID: 325299



Photo 2. View of stormwater issues that persist in the eastern portion of the project area, no BMPs observed.

Inspection Photos
Location Name: DL Gould Flume Canyon 2
Location ID: 325299



Photo 3. Patches of Musk Thistle observed throughout the location.

Inspection Photos
Location Name: DL Gould Flume Canyon 2
Location ID: 325299

3/24/25
20° N



Photo 4. View of access road that remains unreclaimed.