

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#1 overview of
working area of pit.

Mar 17, 2025 12:30:51 PM
40.3080434538424N 107.68941856920719W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#2 overview of pit;
oil and water in pit.

Mar 17, 2025 12:30:49 PM
40.30805158428848N 107.68943382427096W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#3 looking east a
the area of smaller pits
near main gate.

Mar 17, 2025 12:30:17 PM
40.30802861787379N 107.68963012844324W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#4 photo taken
from north east side of
pit. Note:oil and water on
pit.

Mar 17, 2025 12:30:04 PM



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#5 looking east
across the northern
border of pit. Note:
discharge piping.

Mar 17, 2025 12:29:01 PM
40.30776483938098N 107.69022851251066W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#6 discharge
piping.

Mar 17, 2025 12:28:57 PM
40.30776136089116N 107.69023882225156W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



40.30752754770219N 107.69023404456675W
Mar 17, 2025 12:28:25 PM

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#7 photo taken on
west side of pit. Note:
discharge piping.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#8 photo taken
from west side of pit.
Looking east.

Mar 17, 2025 12:28:15 PM
40.30745131429285N 107.69017905928195W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#9 photo taken
from west side of pit
looking north.

Mar 17, 2025 12:28:08 PM
40.3073941078037N 107.6901540812105W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#10 photo taken
inside pit complex looking
west.

Mar 17, 2025 12:27:55 PM
40.30736992601305N 107.69000236876309W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#11 southwest
corner of the pit.

Mar 17, 2025 12:27:37 PM
40.30740919522941N 107.68978888168931W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#12 Looking
northwest across pit.



Mar 17, 2025 12:27:06 PM
40.307504874654114N 107.68950724974275W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#13 looking at the
south end of the pit.

Mar 17, 2025 12:27:03 PM
40.30752922408283N 107.68956894055009W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#14 Photo taken from inside the pit complex, looking to the northeast. Note; rills at front of photo. Water, as evidenced by rills went toward and under the gate in the background of photo.

Mar 17, 2025 12:25:47 PM
40.307535217143595N 107.68929786980152W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#15 Photo taken from inside the pit complex, looking to the northeast. Note; rills at front of photo. rills went toward and under the gate in the background of photo.

Mar 17, 2025 12:25:54 PM
40.30757662374526N 107.68928764387965W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#16 close up of
gate.

Mar 17, 2025 12:26:03 PM
40.307610193267465N 107.6892681978643W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#17 close up of gate in previous pictures 14-16. Note evidence of water leaving pit facility.

Mar 17, 2025 12:26:12 PM
40.30764548107982N 107.68925227224827W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#18 photo taken
from inside pit complex
looking out of complex at
evidence of water leaving
the pit area.

Mar 17, 2025 12:26:23 PM
40.307669998146594N 107.68920533359051W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#19 photo taken
from inside pit complex
looking out of complex at
evidence of water leaving
the pit area.

Mar 17, 2025 12:26:28 PM
40.30766241252422N 107.68920809961855W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles

Location ID: 116587

Remediation Project #: 28244

Inspection Date: 3/17/2025

Photo#20 photo taken
inside pit complex of area
around pit, on the east
side.

Mar 17, 2025 12:26:05 PM
40.30761044472456N 107.68927372992039W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#21 piping on east
side of pit complex



Mar 17, 2025 12:25:23 PM
40.307493642903864N 107.68922151066363W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#22 photo taken
looking southwest across
the access road portion
of the pit complex.



Mar 17, 2025 12:25:17 PM
40.307503868825734N 107.68920013681054W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 3/17/2025

Photo#23 area inside pit complex of the former smaller pits on the southeast side of complex.

Mar 17, 2025 12:25:15 PM
40.30746820382774N 107.68922762945294W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources